





Pododent Motor NSK Japan Bearing Replacement

The ball bearings used by NSK are not stainless, although water flows through the handpiece. Therefore they rust easily. Servicing Costs 500 Euro. But replacement is inexpensive and easy.

Written By: Michael





Arbeite die Schritte in umgekehrter Reihenfolge ab, um dein Gerät wieder zusammenzubauen.

This document was last generated on 2017-06-19 06:32:15 AM.